Summerland Aquatic & Fitness Centre Photos



Current facility



Leaking roof




Condensation and ice build up




Broken laterals



Repairs to hot tub plumbing










Main electrical distribution panel failed and needed to be rebuilt outside of the main panel. Disconnect corroded.



Retrofitted new elbow as they are no longer made in the same size as our current pipes.



Aged HVAC system









Plumbing challenges



